



10/792,357

CofC

18w

David M. Solak
4805 Maple Hill Drive
Seven Hills, Ohio 44131
d.solak@sbcglobal.net
May 24, 2004

Certificate
JUL 07 2004
of Correction

Dear Patent Agent,

I respectfully apologize for not including the patent application number. Here are the original sheets I was sent on May 24, 2004. Enclosed is a copy of the receipt I received from the PTO. I am hoping this is what you need. The patent has not been issued yet. The correction involves the placement of "fire ignites here" on the block diagram. I believe I placed the phrase in the wrong location on the original patent application. You will find three drawings of the block diagram with the "fire ignites here" in the proper location. I hope this is the acceptable way to remedy this problem. If not, please contact me at your convenience.

22387 U.S. PTO
10/792357 ✓

030404

Respectfully,
David M. Solak
Engineer/Inventor

RECEIVED

JUL 16 2004

Technology Center 2600

RECEIVED

JUL 16 2004

Technology Center 2600



UNITED STATES PATENT AND TRADEMARK OFFICE

O I P
MAY 27 2004

COMMISSIONER FOR PATENTS
UNITED STATES PATENT AND TRADEMARK OFFICE
P.O. Box 1450
ALEXANDRIA, VA 22313-1450
www.uspto.gov

PATENT NO.	PATENT DATE 4/26/04
PATENTEE DAVID M. SOLPK	

Paper No.: _____

MAILING DATE

Certificate

APR 30 2004

of Correction


**NOTIFICATION OF RETURN OF PAPERS
RE REQUEST FOR CERTIFICATE OF CORRECTION**

The request for a Certificate of Correction in the above-identified patent is returned herewith, together with the PTOL-1050 (SB/44) forms (if submitted), for the reason(s) checked below.

- 1. The request is unsigned. The request must be properly signed before it will be considered.
- 2. The request does not specifically designate the column and line numbers wherein the errors appear in the patent. A substitute request providing this information is required, for proper consideration.
- 3. The FORM PTOL-1050 (SB/44) submitted with your request is not suitable for printing purposes. See the instructions on the blank Form PTO-1050, enclosed.
- 4. The Patent No., as shown on papers attach, appears to be incorrect, because:
 - a. The Patent No. on the request and on the PTO-1050 do not agree.
 - b. The name of the patentee on the patented file does not agree with that shown on the enclosed papers..
- 5. The record reveals that there is no power of attorney to you in this case. A written power or authorization from the patentee, or assignee, if any, must be submitted, before the request may be considered.
- 6. The request cannot be considered, because the paper indicated below was filed on _____, AFTER payment of the issue fee: [See 37 CFR 1.313(B).]
 - a. Amendment purported to be under Rule 312.
 - b. Assignment.
 - c. Priority papers.
 - d. Other (identify) _____
- 7. Other: NO PATENT NUMBER

A. PLEASE RETURN A COPY OF THIS LETTER TOGETHER WITH THE ENCLOSED PAPERS AS CORRECTED TO ENSURE EXPEDIENT ASSOCIATION WITH THE FILE

B. Enclosed are copies of PTOL-1050 for use in typing the subject matter to be printed on the Certificate.
This will avoid delay in handling request (See 862 O.G.2).


Decisions and Certificate of Correction Branch

FORM PTOL-396 (8/75)



RECEIVED

JUL 16 2004

Technology Center 2600

The following received today:

22387 U.S. PTO
10/792357



Patent application of David M. Solak for
"RF SMOKE SENSING SYSTEM WITH
INTEGRATED SMOKE/HEAT SENSING
CHRISTMAS ORNAMENT TRANSMITTER,"
Consisting of 5 sheets Description, Claims,
Abstract, Declaration signed March 1, 2004
7 sheets formal drawings, small entity declaration
cover sheets and check # 3716 for \$ 420.00

NON-WINTER-HOLIDAY SEASON




FIG. 5



NON-WINTER-HOLIDAY SEASON




FIG. 5

NON-WINTER-HOLIDAY SEASON




FIG. 5

NON-WINTER-HOLIDAY SEASON




FIG. 5

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**

PATENT NO. :

DATED : 9/26/04

INVENTOR(S) : DAVID M. SOLAK

APPLICATION / DRAWINGS

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

NON-WINTER-HOLIDAY SEASON




FIG. 5

Dear Ms or Sir,

I respectfully request to make a correction on my patent application before it possibly issues. If this is not the proper time or way to make a correction discard this document and I will make the correction when the proper time arises if the patent is issued.

Sincerely,

David M. Solak
Engineer/Inventor

Application Title: Smoke Sensing System With Integrated
Christmas Tree Ornament Fire Detector

MAILING ADDRESS OF SENDER: 4805 MAPLE HILL DR. PATENT NO. _____

SEVEN HILLS, OHIO 44131-5916
d.solak@sbglobgl.net

No. of additional copies



This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. :

DATED : 9/26/09

INVENTOR(S) : DAVID M. SOLAK

APPLICATION / DRAWINGS

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

NON-WINTER-HOLIDAY SEASON




FIG. 5

Dear Ms or Sir,

I respectfully request to make a correction on my patent application before it possibly issues. If this is not the proper time or way to make a correction discard this document and I will make the correction when the proper time arises if the patent is issued.

Sincerely,

David M. Solak
Engineer/Inventor

Application Title: Smoke Sensing System With Integrated
Christmas Tree Ornament Fire Detector

MAILING ADDRESS OF SENDER: 4805 MAPLEHILL DR. PATENT NO. 10/792357
 SEVEN HILLS, OHIO 44131-5916
 d.solak@sbccglo.com

No. of additional copies



This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. :

DATED : 4/26/09

INVENTOR(S) : DAVID M. SOLAK

APPLICATION / DRAWINGS

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

NON-WINTER-HOLIDAY SEASON




FIG. 5

Dear Ms or Sir,

I respectfully request to make a correction on my patent application before it possibly issues. If this is not the proper time or way to make a correction discard this document and I will make the correction when the proper time arises if the patent is issued.

Sincerely,

David M. Solak
Engineer/Inventor

Application Title: Smoke Sensing System With Integrated
Christmas Tree Ornament Fire Detector

MAILING ADDRESS OF SENDER: 4805 MAPLE HILL DR. PATENT NO. 10/792357
 SEVEN HILLS, OHIO 44131-5916 No. of additional copies
d.solak@sbccg10.b91.net →

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.